JULY 12, 1995 167 W.CARIBBEAN PORT ST. LUCIE, FL. 34952

FEDERAL COMMUNICATIONS COMMISSION
1919 M STREET, NW
WASHINGTON, D.C. 20554

OI Doe Mo. 75-55

ICC N. . . Fiz.

TO WHOM IT MAY CONCERN:

REF: NOTICE OF INQUIRY TOWARDS PRIVATIZING INSPECTIONS.

I WISH TO MAKE IT VERY CLEAR AT THE START THAT I AM ABSOLUTELY OPPOSED TO PRIVATIZING INSPECTIONS IN ANY SERVICE AND ESPECIALLY THE MARINE SERVICE ... TO CARRY THIS TREND FOWARDS CAN ONLY RESULT IN THE PRIVATIZATION AND EVENTUAL DESTRUCTION OF THE F.C.C. ITSELF...LEADING TO CHAOS, THUS JEOPARDIZING SAFETY OF LIFE AND PROPERTY IN MOST AREAS OF OUR SOCIETY.

WHAT THE F.C.C. IS TALKING ABOUT IN THE NOTICE IS THE YEARLY INSPECTION APPARENTLY SINCE, NOWADAYS, THAT IS THE ONLY ONE THAT THEIR BUDGET PERMITS. THIS INSPECTION CAN TAKE UP TO 6 HOURS SIMPLY BECAUSE IT IS VITALLY NECESSARY TO MAKE SURE THAT THE BATTERIES WHICH SUPPLY THE RADIO ROOM EMERGENCY TRANSMITTER IS CAPABLE OF SIX HOURS CONTINUOUS DUTY WHILE ALSO SUPPLYING THE RECEIVERS, AUTOMATIC ALARM KEYER AT THEIR RATED LOADS AND THE RADIO ROOM EMERGENCY LIGHTING. IN MY OPINION, AND MANY OTHERS IN COMMUNICATIONS THIS MORSE CODE EQUIPMENT IS THE COURT OF LAST RESORT WHEN ALL OTHERS FAIL...AS WAS RECENTLY SHOWN WHEN A US PILOT CAPT. O'GRADY BAILED OUT OVER BOSNIA-SERB COUNTRY-SIDE AND SAVED HIS LIFE USING A SMALL BATTERY-SUPPLIED TRANSCEIVER WITH MORSE TELEGRAPHY CAPABILITY.

IT HAS BEEN SAID THAT SOME SHIPS CAPTAINS, ACCORDING TO THE FCC INSPECTORS, REPORT THAT THE SHIPS MEDIUM RADIOTELEGRAPH INSTALLATION IS USED ONLY DURING THE ANNUAL INSPECTION. TO CLARIFY THIS UNTRUE STATEMENT IT SHOULD BE NOTED THAT ON OIL TANKERS WITH VOLATILE CARGOES, THE TRANSMITTERS FOR OBVIOUS SAFE TY REASONS MAY ONLY BE TESTED AFTER THE CARGO HOSES ARE COMPLETLY DISCONNECTED AND CLEARED... AND ARE SO REPORTED TO THE CAPTAIN AND LOGGED. ON OTHER VESSELS THEY ARE TESTED ONE HOUR OR MORE PRIOR TO UNDOCKING. FURTHERMORE, THE MAIN AND EMERGENCY XMITTERS ARE TESTED ON THE AIR EVERY DAY WHILE THE VESSEL IS AT SEA.

FURTHERMORE, THE ONLY REASON THEY ARE NOT USED MORE FREQUENTLY IS BECAUSE EITHER THE COMPANY OR THE CAPTAIN DO NOT ENCOURAGE THEIR USE PREFERRING TO USE SATELLITE, OR SSB/VOICE OR PERHAPS SITOR OCCASIONALLY. MEDIUM FREQ. IS USED HOWEVER WHEN SAFETY WARRANTS. (CONTINUED PAGE 2

FOR EXAMPLE, WHILE I WAS RADIO-ELECTRONICS OFFICER ON THE MV OMI HUDSON/KNJL DURING THE PERIOD 1992-1994 I HAD OCCASION TO INTERCEPT A NEARBY URGENT SIGNAL FROM A MEXICAN SHORE STATION CALL LETTERS XFM MANZANILLA . AS A RESULT WE WERE ALERTED TO A POTENTIALLY DANGEROUS SITUATION NOT TOO FAR FROM OUR VESSEL AS WE WERE PROCEEDING SOUTH TO THE PANAMA CANAL. IT SHOULD ALSO BE NOTED THAT THIS IMPORTANT INFORMATION WAS \*\*\*NOT\*\*\* HEARD ON SATELLITE NOR WERE WE IN RANGE OF VHF EQUIPMENT. THE 2182KHZ VOICE EQUIPMENT WAS UNUSABLE DUE TO HVY STATIC. IT WAS ONLY 500KHZ THAT GOT THRU! THAT IS PROBABLY THE REASON HPP RADIO PANAMA USES 500 KHZ MORSE TO ALERT SHIPS IN BOTH THE ATLANTIC AND PACIFIC AREAS OF DISTRESS TO LARGE AND SMALL SHIPPING... WHICH IS NEARLY A DAILY OCCURENCE

WITH REFERENCE TO THE STATEMENT THAT THE INSPECTION MAY BE LESS COMPLICATED WITH GMDSS EQUIPMENT AND THEREFOR CORNERS CAN BE CUT, THIS REASONING IS FAULTY ON A NUMBER OF FRONTS. FIRST THE MORE AUTOMATED THE EQUIPMENT IS THE MORE VARIABLES NECESSARILY ARISE. HAVING AN OPERATOR/MAINTAINER LICENSE GIVES ME A LITTLE FAMILIARITY WITH THE SUBJECT...AND I HAVE NO REASON TO BELIEVE THAT A PRIVATE GROUP CAN DO BETTER OR AS WELL AS THE FCC INSPECTORS. THE SHIPPING COMPANIES ENVISION HAVING NO TECHNICALS WHO ARE QUALIFIED TO DO SUCH REPAIRS AS REQUIRED AT SEA AND CERTAINLY THE FCC INSPECTORS WOULD BE NEEDED TO MONITOR COMPLIANCE. IN FACT, WHILE AT SEA THE SCENARIO WOULD BE A BRIDGE PERSON, CAPTAIN, MATE OR SEAMAN WHO ALONG WITH DOING THEIR OWN JOB WOULD ALSO MULTITASK WITH THE GMDSS ... AND IN AN EMERGYOU WOULD CERTAINLY KNOW WHO WOULD BE THE LOSER ... HUMAN LIVES!

IN THIS DAY AND AGE , WHEN WE HEAR OF MAJOR MARITIME DISASTERS ALMOST EVERY WEEK , IT SHOULD BE CLEAR THAT STUPID BUDGET-CUTTING IS A FALSE ECONOMY WHEN IT RESULTS IN HUGE LOSSES IN HUMAN LIFE AND THE F.C.C. SHOULD SPEAK OUT AGAINST FALSE ECONOMY OR BE COLORED WITH THE SAME BRUSH AS THOSE OPERATORS WHO PLAY THE INSURANCE GAME FOR BLOODY PROFITS.

I AM SENDING A COPY OF THIS LETTER TO MY SENATORS AND CONGRESSMAN AND I HOPE, THAT IN THE INTERESTS OF THE PEOPLE AFFECTED, THE FCC WILL RELEGATE THE NOTICE OF INQUIRY TO THE NEAREST WASTEPAPER BASKET AND GO ABOUT ITS USEFUL WORK AS ALWAYS.

ENCLOSURE; COPIES OF PERTINENT RADIO LOG OF JUNE 27,1993
ORIGINAL DISTRESS LOGS WERE SENT TO MACKAY RADIO
AT CONCLUSION OF VOYAGE.

SINCERELY YOURS;

ARNE F. HANSON MREO



## Radio Log

## INSTRUCTIONS

- 1. Forward logs to Mackay Communications 24 hours after end of voyage.
- 2. Bind pages together with title page.
- 3. Full signature required going on and off watch.
- An entry is to be made at least every 15 minutes when on watch and during silent periods.
- 5. No erasures or obliterations permitted.
- 6. Copy traffic lists daily.

ESSEL	MV OM	I HUDS	ON		CALL LE	TTERS KNJL DATE JUNE 27 1993 SHEET NO. 22	
DAY OF	G.M.T.	STATION CALLED		STATION CALLING		PARTICULARS OF COMMUNICATIONS	
MONTH		Call	Frequency	Call	Frequency		
	1400- 15-	15			500	NO SIGNALS HEARD THIS LPERIOD	
_27.TH	15.	10				SILENT PERIOD OBSERVED NO SIGNALS HEARD	
	18-		Ì		1 1	NO SIGNALS HEARD THIS PERIOD	
	35	CQ		WLO	12990.5	TFC LIST NIL FER KNJL	
	30-	45			500	NO SIGNALS HEARD THIS PERIOD	
	45-	48	<del></del>	<del> </del>		SILENT PERIOD OBSERVED NO SIGNALS HEARD	
	48- 1500-	1500			"	NO SIGNALS HEARD THIS PERIOD NO SIGNALS HEARD THIS PERIOD	
	1500	10		<del> </del>	<del> </del>	SILENT PERIOD OBSERVED NO LSIGNALS HEARD	
	ì	(			, ,	·	
NATE.	18-	20	<del></del>	<del></del>		NO SIGNALS HEARD THIS PERIOD	
NOTE:						WE ARE OFF MANZANILLA MEXICO AND CIRCLING SINCE THIS EARLY AM. AWAITING TO PUT ASHORE A CREW MEMBER NEEDING	
					10000	MEDICAL ATTENTION.	
	35	CO	ļ	WLO	12990.		
	30-		1		500	NO SIGNALS HEARD THIS PERIOD	
	45-	48		<u> </u>		SILENT PERIOD OBSERVED NO SIGNALS HEARD	
	50				,,	TESTED RADIO ROOM EMERG. LITES , OPERATION OK BOTH SWI	
	菱	1555				TESTED RADIO ROOM EMERG. RECEIVER, OPERATION NORMAL AS	
	ł		1			COMPARED TO MAIN RECEIVER. OPERATES OK ON AC AND DC EN	
						ENCY BATTS. VOLTAGE 14.7V. ON TRICKLE CHARGE.	
	1558		}	WWV	10 MHZ		
	1548-	1600			500	NO SIGNALS HEARD THIS PERIOD	
	1600-	15			"	NO SIGNALS HEARD THIS PERIOD	
	15-	18	ļ		ļ	SILENT PERIOD OBSERVED NO SIGNALS HEARD NO SIGNALS HEARD THIS PERIOD	
	18-		1	1	"	NO SIGNALS HEARD THIS PERIOD	
	30-		ļ		12990.		
	35	CQ		WLO		1	
	30-		ļ	<u> </u>	500	NO SIGNALS HEARD THIS PERIOD	
	45-	1			10570 0	SILENT PERIOD OBSERVED NO SIGNALS HEARD	
	55	ca		KFS	12578.9	TEC LIST , NIL FER KNJL , RPT OF WX WE COPIED EARLIER	
	2000	1700			500	WLO. RE. TROPICAL DEPRESSION 3E	
·	1648-			ļ	500	NO SIGNALS HEARD THIS PERIOD	
	00-	15		i	"	NO SIGNALSD HEARD THIS PERIOD	
	15-	18			1	SDILENT PERIOD OBSERVED NO SIGNALS HEARD	
	25	V		KNJL	500	TESTED EMERG. XMITTER, ON EMERG. ANTENNA. ANTENNA CUR	
				<u> </u>		2.8 AMPS. KEYING OK. KEYDOWN E. 12.7VOLTS.	
	26			İ	410	TESTED AUTO ALARM SIGNAL GENERATOR, USED EMERG. XMITT	
		ļ	ļ	<u> </u>	<u> </u>	SENT 1 4 SEC DASH , ONE 1 SEC SPACE , ONE 2 SEC DASH,	
					F00	TIMING IS ACCURATE, MIN. RADIATION , ANTENNA DETUNED	
		30	ļ		500	NO SIGNALS HEARD THIS PERIOD	
		45	1		",	NO SIGNALS HEARD THIS PERIOD	
		48			1	SILENT PERIOD OBSERVED NO SIGNALS HEARD	
	48-	1800		{	"	NO SIGNALS HEARD THIS PERIOD	
NOON	1800		<u> </u>	<b></b>		OFF WATCH OF Hause AUTO ALARM ON,	
500	,	ANTI C	LCV 30	h7. 10	A.L.C.	DELAYING TEST BECAUSE WE ARE NOW INSIDE THE HARBOR	
POSN.		MILLO	MEX. 19	<b>ф</b> 3м, 10		OF MANZANILLO MEXICO.	
	2000				500	ON WATCH AUTO ALARM OFF	
				ļ <u> </u>		PILOT LEFT SHIP WE NOW UNDERWAY FOR PA	
	2010	ca		WLO	12990.5	CREW MEMBER NEEDING MEDICALATTENTION WAS PUT ASHORE. COPIED FROM DISC THE WX REPORT FM WLO AT 1935Z REF;	

DAY	,	STATION	CALLED	STATION	CALLING	
OF	G.M.T.	Call	Frequency	Call	Frequency	PARTICULARS OF COMMUNICATIONS
MONTH	2000-1		/		500	NO SIGNALS HEARD THIS PERIOD
27тн		18			"	SILENT PERIOD OBSERVED ET NO SIGNALS HEARD
	18	F30			"	NO SIGNALS HEARD THIS PERIOD
	35			WLO	16990.	TEC LIST NIL FER KNUL
	30	-45			500	NO SIGNALS HEARD THIS PERIOD
	43			NMC	17149.	COPIED WX FAX OF AREA 22 DEGREES N TO EQUATOR IN PACIFIC SHOWING THE TROPICAL DEPRESSION THREE E
						PACIFIC SHOWING THE TROPICAL DEPRESSION THREE E
	. 45				500	SILENT PERIOD OBSERVED NO SIGNALS HEARD
		-2100			"	NO SIGNALS HEARD THIS PERIOD
	2100-			ļ	"	NO SIGNALS HEARD THIS PERIOD
	15-		]	ļ	"	SILENT PERIOD OBSERVED NO SIGNALS HEARD
	18=	80			"	NO SIGNALS HEARD THIS PERIOD
	35	_ ca		WLO	16990.	
	30 <del>-</del> 45-	15		<del> </del>	590	NO SIGNALS HEARD THIS PERIOD
	45~	H8 D200			, ,	SILENT PERIOD OBSERVED NO LSIGNALS HEARD
		2200		ļ	,,,	OFF WATCH A FAMILY AUTO ALARM ON TESTED
	2200					IT 4 DASHES TO RING ALL BELLS . ALSO TESTED HAND RIN
		<del> </del>	<del> </del>	<b></b>		ER PHONE TO BRIDGE. OPERATES OK.
	05			1	сн16	TESTS OF ROO ROOM VHF TRANSCEIVER AND TESTS OF TWO BRID
					VILAV	VHF TRANSCEIVERS SHOW THEM ALL TO BE OK.
	12		1	}	2182	TESTED RADIO ROOM 2182KHZ WATCHKEEPING RECEIVER AND
	<del></del>					FOUND TO BE OPERATING NORMALLY. SQUELCH OK. REMOTE UNI
			_			
28тн	0000				500	ON BRIDGE OK HOUSE AUTO ALARM OFF
	00-	15			"	NO SIGNALS HEARD THIS PERIOD QRND
		18		1		SILENT PERIOD OBSERVED NO SIGNALS HEARD
	22	WLO	16812.	KNJL	16688.8	
	24	KNJL	16688.	\$ WLO	16812.9	REF: 019155 TIME: 28:0024z (QSL)
	18-	30			500	NO SIGNALS HEARD THIS PERIOD
	55	}				TESTED EMERG. BATTS. TOTAL E 14.7 VOLTS PILOT CELL #2
						1.45V ON TRICKLE CHARGE POLARITY CORRECT. WATER LEVEL
	30-45		{		500	NO SIGNALS HEARD THIS PERIOD
	45	48	<del></del>	<del></del>	,,,	SILENT PERIOD OBSERVED NO SIGNALS HEARD GRN4
	48 49	XXX		XFM	479	QSW 480??
	49	XXX	<del> </del>	XEM	4/9	LAT 17-41.5N AND LONG 102-06.0W THE VESSEL TANK/
						BETULA/? IN DANGER OF SINKING, CARGO ON BOARD 4000
		<del> </del>		<b></b>		TONS OF SULPHURIC ACID AND THERE ARE SULPHUROUS  FUMES? ON THE AIR- PLEASE KEEP OUT THIS AREA.
		{	{	1	}	THE VESSEL IS TOWED BY TUG /U?/MAL HARBOUR MASTER
	<del></del>	<del> </del>	<b></b>	<b> </b>		LAGARO CARDENAS AR GRU? 500 4/8/10 MHZ
				1	}	FROWER CHEMINS HE SEC 1/0/10 MILE
	0055?	XFM	1	KNJL	500	PSE RPT THE XXX (I, WANTED VERIFICATION OF POSITION
	00001	71.11				AND WA VESSEI)
	56	KNJL	1	XFM	,	(REPEATED POSN AND TOWED) QRN QUITE BAD AND HIS SIG
						WAS VARYING.
		KNJL		XFM	"	PSE QRA? I REPLIED MV OMI HUDSON AND THANKED HIM GAVE
					1	HIM QSL OF XXX. THEN CLEARED.
	0000			1		OUR POSITION IS 182/N, 10356W
	0100-		<b></b>	ļ	500	NO OTHER SIGNALS HEARD THIS PERIOD
	15-	<b>F</b> 8	1	1	"	SILENT PERIOD OBSERVED NO SIGNALS HEARD
	18-			<b></b>	l	NO SIGNALS HEARD THIS PERIOD
!	35	CQ		.MFO	16996.	TEC LIST NIL KNUL BUT COPIED ALL WX PERTAINING TO
		<b></b>	<del> </del>	<b> </b>	}	TROPICAL DEPRESSION THREE E. WHICH IS COMING QUITE
	30-	45	1	1		CLOSE TO US PERHAPS.
			<del> </del>	<del> </del>	F00	NO SIGNALS HEARD THIS PERIOD
	45-	48 0200	[	[	500	SILENT PERIOD OBSERVED NO SIGNALS HEARD NO SIGNALS HEARD THIS PERIOD
		UZUU	<del> </del>	<del> </del>	500	OFF WATCH ALARM ON
	0200		)	1		THEN Y
		L	<u> </u>			<u> </u>